

# EHC ASSOCIATES

ENVIRONMENTAL CONSULTANTS & ABATEMENT CONTRACTORS

August 17, 2016

Ms. Joanne Slichter  
Wilson School District  
2601 Grandview Blvd.  
West Lawn, PA 19609-1324

Re: **Wilson School District**  
**10/29/18 Lead In Water Testing Services**  
EHC Project No.: 008721-006

Dear Ms. Slichter:

Please review the enclosed analytical report in regard to the water samples collected from the Wilson School District on October 29, 2018. The samples were analyzed for lead content by Suburban Test Laboratory using the EPA 200 Method. The following provides a summary of the results:

## WILSON SENIOR HIGH SCHOOL – UPPER HOUSE

| <u>Sample Number/Sample Location</u> | <u>Results</u> |
|--------------------------------------|----------------|
| #1 Water Fountain – A-500 Hall       | 0.001 mg/L     |
| #2 Water Fountain – E-400 Hall       | <0.001 mg/L    |
| #3 Sink – Nurse's Office             | <0.001 mg/L    |
| #4 Sink – Cafeteria                  | <0.001 mg/L    |

## WILSON SENIOR HIGH SCHOOL – LOWER HOUSE

| <u>Sample Number/Sample Location</u> | <u>Results</u> |
|--------------------------------------|----------------|
| #5 Stadium Concession Sink           | <0.001 mg/L    |
| #6 Sink – Locker Room                | <0.001 mg/L    |
| #7 Sink – Kitchen                    | <0.001 mg/L    |
| #8 Sink – Outside Main Office        | <0.001 mg/L    |

## BERKSHIRE HEIGHTS ELEMENTARY SCHOOL

| <u>Sample Number/Sample Location</u> | <u>Results</u> |
|--------------------------------------|----------------|
| #9 Sink – Kitchen                    | 0.003 mg/L     |
| #10 Fountain – Near Room 4           | 0.005 mg/L     |
| #11 Sink – Boy's Bathroom (Basement) | <0.001 mg/L    |

2502 HORSESHOE ROAD, LANCASTER, PA 17601 ♦ 717-656-3008 ♦ FAX: 717-656-7134  
EMAIL: OFFICE@EHCASSOCIATES.COM ♦ WWW.EHCASSOCIATES.COM

Environmental Design • Consulting • Surveys • IAQ • Monitoring • Abatement & Demolition  
Specializing in the removal of Asbestos, Lead, Mold and other hazards in the built environment.

0.001 mg/L

**SPRING RIDGE ELEMENTARY SCHOOL**

| <u>Sample Number/Sample Location</u> | <u>Results</u> |
|--------------------------------------|----------------|
| #13 Sink – Kitchen                   | <0.001 mg/L    |
| #14 Sink – Faculty Room              | 0.001 mg/L     |
| #15 Sink – Room 117                  | <0.001 mg/L    |
| #16 Fountain – Near Nurse            | <0.001 mg/L    |

**WHITFIELD ELEMENTARY SCHOOL**

| <u>Sample Number/Sample Location</u> | <u>Results</u> |
|--------------------------------------|----------------|
| #17 Sink – Kitchen                   | <0.001 mg/L    |
| #18 Fountain – Hall at Main Office   | <0.001 mg/L    |
| #19 Fountain – Hall at B104          | <0.001 mg/L    |
| #20 Sink – Bathroom at L120          | <0.001 mg/L    |

**SOUTHERN MIDDLE SCHOOL**

| <u>Sample Number/Sample Location</u>        | <u>Results</u> |
|---|----------------|
| #21 Sink – Transportation Building          | <0.001 mg/L    |
| #22 Sink – Kitchen                          | 0.002 mg/L     |
| #23 Fountain at Gym                         | <0.001 mg/L    |
| #24 Sink – Boy’s Bathroom at 104 LL Commons | <0.001 mg/L    |

**CORNWALL TERRACE ELEMENTARY SCHOOL**

| <u>Sample Number/Sample Location</u> | <u>Results</u> |
|--------------------------------------|----------------|
| #25 Fountain - At Room 102           | <0.001 mg/L    |
| #26 Fountain – At Room 111           | <0.001 mg/L    |
| #27 Fountain – At Room 132           | <0.001 mg/L    |
| #28 Sink – Nurse’s Office            | 0.001 mg/L     |

**SHILOH HILLS ELEMENTARY SCHOOL**

| <u>Sample Number/Sample Location</u> | <u>Results</u> |
|--------------------------------------|----------------|
| #29 Sink – Office                    | <0.001 mg/L    |
| #30 Sink – Room 163                  | <0.001 mg/L    |
| #31 Sink – Room 101                  | 0.001 mg/L     |
| #32 Sink – Kitchen                   | 0.001 mg/L     |

**Wilson School District  
10/29/18 Lead in Water Testing Services  
Page 3 of 3**

**GREEN VALLEY ELEMENTARY SCHOOL**

| <u>Sample Number/Sample Location</u> | <u>Results</u> |
|--------------------------------------|----------------|
| #33 Sink – Office Bathroom           | 0.002 mg/L     |
| #34 Sink – Room 159                  | 0.002 mg/L     |
| #35 Sink – Room 111                  | 0.002 mg/L     |
| #36 Sink – Kitchen                   | 0.007 mg/L     |

**WEST MIDDLE SCHOOL**

| <u>Sample Number/Sample Location</u> | <u>Results</u> |
|--------------------------------------|----------------|
| #37 Sink – Kitchen                   | 0.001 mg/L     |
| #38 Fountain – At SGI 120            | <0.001 mg/L    |
| #39 Sink – At Nurse's                | 0.003 mg/L     |
| #40 Fountain – At SGI 138            | <0.001 mg/L    |

**LOWER HEIDELBERG ELEMENTARY SCHOOL**

| <u>Sample Number/Sample Location</u> | <u>Results</u> |
|--------------------------------------|----------------|
| #41 Fountain – South End             | 0.002 mg/L     |
| #42 Sink – Kitchen                   | 0.003 mg/L     |
| #43 Sink – Office                    | <0.001 mg/L    |
| #44 Sink – Janitor's Closet          | 0.001 mg/L     |

Laboratory analysis indicates **the water samples collected from all of the above locations are below the recommended action level of 0.015 mg/L.**

Please review the enclosed analytical report and contact our office with questions, or if further information is needed.

Sincerely,



Mark Andrechik  
Inspector

Encl.'s: Laboratory Analysis Report  
Invoice No.: 008721-006